

Version Info:

1. Firmware adapted for InSight S285(2.8mm)(UN) 1.0/1.6, InSight S285(4mm)(UN) 1.0/1.6, InSight S385(2.8mm)(UN) 1.0/1.6, InSight S385(4mm)(UN) 1.0/1.6, InSight S485(2.8mm)(UN) 1.0/1.6, InSight S485(4mm)(UN) 1.0/1.6, VIGI C385(2.8mm)(UN) 1.0, VIGI C385(4mm)(UN) 1.0, VIGI C485(2.8mm)(UN) 1.0, VIGI C485(4mm)(UN) 1.0.
2. Compatible APP versions: VIGI APP (iOS: 2.6.16, Android: 2.6.25).

New Feature:

1. Added remote registration to support adding IPC to NVR over public networks. (It needs to be used in combination with VIGI NVR)
2. Added support for RTMP.
3. Added support for motion recording mode.
4. Added time format settings.
5. Added support for 802.1x.
6. Added support the VIGI APP to scan the QR code to retrieve the password.
7. Added support for one-click arming and disarming function.
8. Added support for VIGI OpenAPI.
9. Added support for users to set whether to automatically change to static IP when added by ONVIF.
10. Added support VMS AI Snapshot. (It needs to be used in

combination with VIGI VMS)

11. Added support for VIGI VMS to retrieve human and vehicle attributes.
12. Added support for web playback from SD card storage.
13. Added support for the Arabic language on the web interface.
14. Added customizable settings for Light Alarm and Sound Alarm.
15. Added support for log server.
16. Added support for detection rule frame in smart frame.
17. Added support for polygon drawing in event areas.
18. Added support for scene mode settings.
19. Added a toggle switch for Object Filter in Event Settings.

Enhancements:

1. Optimized the web initialization process.
2. Custom Audio feature of Sound Alarm supports wav and mp3 format audio.
3. Optimized remote live view and playback performance for VIGI APP and VMS.
4. Optimized mosaic display in Privacy Mask.
5. Optimized fast playback performance.
6. Optimized the unbinding rules for cloud accounts.

Bug Fixes:

1. Fixed some minor bugs.

2. Fixed several security issues.
3. Fixed some compatibility issues.

Notes:

1. Version 2.5.0 supports cloud upgrade or manual upgrade to this version of the firmware that has been released for all models below version 2.5.0. After upgrading to this version, downgrading is not possible.